





TECHNICAL REPORT RL-80-8

FREE AIR PLUME OVERPRESSURE FOR 2.75 INCH ROCKET MOTORS MARK 40 AND MARK 66

Robert Bergman
Donald Davis
Ground Equipment and Missile Structures Directorate
US Army Missile Laboratory

13 March 1980





U.S. ARMY MISSILE COMMAND

Redstone Arsenal, Alabama 35809

Approved for public release; distribution unlimited.

Reproduced From Best Available Copy

DIE FILE CO

1021, 1 JUL 79 PREVIOUS EDITION IS OBSOLETE

80 5 19 241

DISPOSITION INSTRUCTIONS

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED. DO NOT RETURN IT TO THE ORIGINATOR.

DISCLAIMER

THE FINDINGS IN THIS REPORT ARE NOT TO BE CONSTRUED AS AN OFFICIAL DEPARTMENT OF THE ARMY POSITION UNLESS SO DESIGNATED BY OTHER AUTHORIZED DOCUMENTS.

TRADE NAMES

USE OF TRADE NAMES OR MANUFACTURERS IN THIS REPORT DOES NOT CONSTITUTE AN OFFICIAL ENDORSEMENT OR APPROVAL OF THE USE OF SUCH COMMERCIAL HARDWARE OR SOFTWARE.

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

	DOCUMENTATION PA		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2.	GOVT ACCESSION NO	. 3. RECIPIENT'S CATALOG NUMBER
RL-80-8	A	D-AO84 418	
FREE AIR PLUME OVE MOTORS MARK 40 ANI	ERPRESSURE FOR 2.75	INCH ROCKET	TECHNICAL REPORT
7- AUTHOR(A)			8. CONTRACT OR GRANT NUMBER(*)
Robert Bergman Donald Davis			S. CONTRACT ON ORDER HOMESTA
9. PERFORMING ORGANIZA Commander	TION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
US Army Missile Co ATTN: DRSMI-RI. Redstone Arsenal,			
11. CONTROLLING OFFICE			12. BESON ONTE
Commander US Army Missile Co ATTN: DRSMI-RPT	nomand	(11)	13 Maradaci 89
Redstone Arsenal.	Alabama 35809		19 15. SECURITY CLASS. (of this report)
MUNITURING AGENCY N	AME & ADDRESS(II different fr	controlling Office)	
		24 /	UNCLASSIFIED
	(12/0	×1-1	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEM	ENT (of this Report)		
17. DISTRIBUTION STATES	DKSMI	Block 20, Il different tr	Tool Report)
18. SUPPLEMENTARY NOT	25		
19. KEY WORDS (Continue on	reverse side if necessary and i	dentify by block number	r)
Plume Pressure Rocket Overpressur 2.75 Inch Rocket	ce		
/			
.f.a.	reverse side if necessary and in		
inch rocket motors	s MARK 40 and MARK 6	66. Data were	ast overpressure of the 2.75 collected for single and e maps" were generated to
display the result		ets. riessui	- mar- 9

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

THE PROPERTY OF THE PROPERTY O

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)	
SECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)	
	ļ
	į
	- 1
	ı
	i
	[
	1
	j
	į
	Į
	i
	ł
	- 1
	i
	ļ
	i
	ì
	- 1
	1
	1
	- 1
	i
	- 1
	1
	- 1
	- 1
	į
	- 1
	1
	t
	1
	1
	- 1
	ĺ
	i
	- 1

CONTENTS

Section	on	Page
I.	Introduction	3
II.	Test Setup	3
III.	Test Sequence	8
IV.	Test Results	8

Accese	ion For	
NTIS	GRALI	
DDC TA	33	
Unanno	unced	
Justif	ication	
Ву		
Distri	butien/	خسسانا و منوسون مورد و موسود
Avnil	ability	dedes
}	Availa:	
Dist	speci	al
]	
H		
1 / 1		

ILLUSTRATIONS

Figure				Pag€
1.	2.75 Inch Rocket Performance			4
2.	Test Setup at Test Area 1	•	•	5
3.	2.75 Inch Rocket Plume Pressure Test,			
	Instrumentation Setup		•	6
4.	2.75 Inch Rocket Plume Pressure Test, Single			
	Fire Instrumentation Positions	•	•	7
5.	Firing Adapter to Permit Use of MK66 Rockets			
	in M-200Al and M-158Al Launchers	•	•	9
6.	2.75 Inch Rocket Plume Pressure Test, Ripple			
	Fire Instrumentation Positions	•		10
7.	2.75 Inch Rocket Plume Pressure Test, MK40			
	Single Fire Pressure Map	٠	•	11
8.	2.75 Inch Rocket Plume Pressure Test, MK66			
	Single Fire Pressure Map	•	•	12
9.	2.75 Inch Rocket Plume Pressure Test, Round			
	No. 5, MK66 Motor	•	•	15
10.	2.75 Inch Rockei Plume Pressure Test, Mk66			
	Motor Ripple Fire Pressure Map	•		16
11.	2.75 Inch Rocket Plume Pressure Test, MK40			
	Motor Ripple Fire Pressure Map	•	•	1 7

I. INTRODUCTION

Questions have risen for some time concerning the overpressure which is generated by launching 2.75 inch rocket motors. The US Army Missile Command was assigned the task to define the overpressure field which is created by both single and ripple rocket firings. Tests were conducted in October 1979 in order to generate overpressure data for two different 2.75 inch rocket motors. One of the rocket motors is the current Mark 40 (MK40) and the other is the Mark 66 (MK66) which is under development.

The US Navy is developing the MK66 rocket motor which has a higher thrust and velocity to achieve a longer range. The relative acceleration curves for both rocket motors are shown on Figure 1. The US Army is adapting the MK66 for Tri-service use which will allow launcher interoperability and improved accuracy when fired from a hovering helicopter.

Attack helicopter designers are concerned about the rocket motor plume overpressure levels because overpressure can affect aircraft design. The AH-1S TOW-COBRA was redesigned to withstand the blast overpressure of the TOW launch motor. Data generated in 1969 by Southwest Research Company under Contract No. DAAD05-67-C-0201 indicated a pressure of 6.5 psi on the helicopter tailboom. The purpose of the testing discussed in this report was to generate comparative data.

II. TEST SETUP

Testing was conducted at Test Area 1 of Redstone Arsenal, Alabama on 31 October 1979 (see Figure 2). Figure 3 depicts the test setup for the initial rocket firing and Figure 4 is an all inclusive diagram of the test setups for the various rocket firings. Instrumentation consisted of four temperature probes and four pressure transducers all of which were mounted on a "rake" and moved for each firing to establish the field for temperature and overpressure. During testing, the heat flux was too low to be recorded; therefore, temperature will not be discussed further. One pressure transducer was placed even with the front of the launcher and three feet off the center of the firing tube. The pressure transducers were the type which are used to measure sound decibels and then the decibels were converted into overpressure in pounds per square inch.




Figure 1. 2.75 inch rocket performance.





Figure 2. Test setup at test area 1.






Figure 4. 2.75 inch rocket plume pressure test, single fire instrumentation positions.

Two launchers were used in conducting these tests. For single round firings the M-158Al, 7 tube launcher, was used and the M-200Al, 19 tube launcher, was used for ripple firings. A change was made between the M-158Al and M-200Al launchers to accommodate parallel testing; however, this change had no effect upon the results of the overpressure tests.

The MK40 rockets were fired using the standard firing contacts of both launchers; however, the MK66 rockets were slightly modified with "rig-tail" firing contacts. The "pig-tail" consisted of a length of 22 gage wire, a pushon sheet metal nut (trade name Tinnerman) and an AMP tap connector. The modification to the MK66 rockets permitted firings without modification to the launcher. See Figure 5 for the modification.

The launchers were mounted on a standard bomb rack which was adapted for ground firings. Rockets were fired at 15 degrees elevation to control the impact area.

III. TEST SEQUENCE


The test hardware was setup with the rake perpendicular to the line-of-sight, one MK40 rocket was fired to adjust the calibration of the pressure transducers, and all single round firings were completed first.

The testing proceeded as follows: The rake was moved back in 30 degree increments and one MK40 and one MK66 rocket was fired for each position. When the rake was set parallel to the line-of-sight, it was offset 24 inches from the launch tube center line to prevent damage to the transducers.

The rake was set at 45 degrees to the line-of-sight for the ripple firings. The first of two six-round ripple firings consisted of MK66 motors and the second of the MK40 motors. See Figure 6.

IV. TEST RESULTS

The pressure data acquired during the test is shown in Table 1. The pressure map resulting from the single MK40 firings is shown on Figure 7. The similar pressure map from MK66 firings is shown on Figure 8. Figure 9 shows the general pressure trace during the firing of round number 5 which was a MK66 motor. The quantitative values shown in Table 1 are peak pressures which occurred



Firing adapter to permit use of MK66 rockets in M-200Al and M-158Al launchers. Figure 5.

A CANAL STREET





Figure 6. 2.75 inch rocket plume pressure test ripple fire instrumentation positions.




⊙ 0.58 psi

O 0.23 psi

⊙0.34 psi

Figure 7. 2.75 inch rocket plume pressure test, MK40 single fire pressure map.



⊙0.73 psi

⊙0.46 psi

⊙0.53 psi

2.75 inch rocket plume pressure test, MK66 Figure 8. single fire pressure map.

TABLE 1. MK40/MK66 ROCKET MOTOR PLUME PRESSURE TEST

the second secon


NO.	KOCK E.I.	RAKE		READINGS (psi	(psi)	Í	TIME
	TYPE	POSITION (deg)	P ₁ (FRONT)	P ₂	P3	24	DELAY (P1-P2)
-	MK 40			•	2		0
2.	MK40				~		0
3.	MK66			•	m		0
4.	MK40	9	0.53	0.17	0.18	0.12	100 msec
5.	MK66			4.	\sim		75 msec
•9	MK40			0.44	m		100 msec
۲-	MK66			(1)	~		75 msec
<u>α</u>	MK40	O			5		100 msec
9.	MK 66	0		(1)	~		80 msec
10-1	MK66	45		(1)	9		80 msec
10-2	MK 66	45		•	S		80 msec
0	MK66	45	0.43	. 54 (J		80 msec
10-4	MK66	45		0,51(2)	S		80 msec
-0	MK66	45		, 68 (4		80 msec
- 1	MK66	45	0.48	, 59 (4		80 msec
4	MK40	45		4.	\sim		100 msec
1	MK 40	45	•	S	4	\sim	100 msec
- 1	MK40	45	٣.	0.43	\sim	m	100 msec
11-4	MK40	45	•	0.48	-	0.32	100 msec
- 1	MK 40	45	ς,	•	4	\sim	100 msec
1	MK 40	45	0.30	0,36	0.35	0.28	100 msec

(1) Maximum data points are difficult to measure. (2) Basic data line was in sinusoidal excursions. Notes:

approximately 50 milliseconds after ignition as shown on Figure 9. The peak pressures are virtually instantaneous and the trend of the pressure profile is below that of the peak pressure listed.

Figures 10 and 11 show the pressure readings from the MK66 and MK40 ripples respectively. The ripple rate was nominally 167 milliseconds (msec) so the pressure trace from one rocket would decay before the next rocket pressure would be recorded.

It should be noted that the highest overpressure observed during these tests was an order of magnitude less than the overpressure produced by the TOW tests.



2.75 inch rocket plume pressure test, round No. 5, MK66 motor. Figure 9.

A LONG CONTRACTOR OF THE SERVICE OF




Figure 10. 2.75 inch rocket plume pressure test, MK66 motor ripple fire pressure map.




Figure 11. 2.75 inch rocket plume pressure test, MK46, motor ripple fire pressure map.

DISTRIBUTION

·	No. of Copies
Defense Technical Information Center Cameron Station	
Alexandria, Virginia 22314	12
US Army Materiel Systems Analysis Activity ATTN: DRXSY-MP	1
Aberdeen Proving Ground, Maryland 21005	
IIT Research Institute ATTN: GACIAC 10 West 35th Street Chicago, Illinois 60616	1
Commander US Army Materiel Development and Readiness Command ATTN: DRCRD DRCDL 5001 Eisenhower Avenue Alexandria, Virginia 22333	1
DRSMI-LP, Mr. Voigt -R, Dr. Kobler -U -UR, Mr. Bergman -RL -RLH, Mr. Davis -RPR -RPT (Record Set) (Reference Set)	1 1 8 1 8 5 1

Preceding Page Blank